

Technical Data Sheet

96-73121 Phoenix 8610, 8611, 8612 Latch Upgrade

Date: 11/14/2005

Page: 1 of 1

MATERIALS REQUIRED:

5010-077 Latch
5010-081 Crank
5240-138 Spring
5021-032 Washer
4500-2976 Setscrew
4700-0790 Spacer- 4x

TOOLS REQUIRED:

5/32" Allen wrench

PROCEDURE:

1. Remove and discard the old door latch assembly by loosening the two setscrews.
2. Install the new latch assembly as shown below. Start out with one spacer on the inside of the door. The crank now threads onto the latch so adjust the crank so there is approximately 1/8" between the crank and the washer.
3. Align the setscrew hole in the crank with the flat on the latch shaft and insert and tighten the setscrew.
4. Check door seals using the "dollar bill test." Shut the door on a dollar bill. If the bill pulls out without any resistance, then your stove's door isn't sealed properly. Spacers can be added or removed to adjust gasket pressure.

